

Spare parts list

Item	Part Number	Description	Illustration
1	2 609 000 418	Housing Section GREEN	1
2	2 609 000 623	Field 230V	1
5	2 604 460 260	Power supply cord H05 VV-F EU 2,7m 2 x 0,75mm	1
6	2 609 002 019	Grommet	1
7	2 601 035 004	Cable Clip	1
9	2 609 000 521	Manufacturer's nameplate PSS 200 AC	1
13	2 600 905 078	groove ball bearing	1
14	2 600 905 052	groove ball bearing 8x22x7	1
15	2 609 000 355	Fan	1
19	2 603 490 022	Screw 4x16	1
21	2 609 000 362	Switch Slide	1
28	2 600 905 045	groove ball bearing 12x28x8	1
30	2 603 490 021	Torx Oval-Head Screw 4x12	1
34	2 609 000 376	Clamping Saddle	1
35	2 609 003 061	Felt Washer	1
49	2 609 001 762	O-Ring	1
50	2 609 000 356	Dust container	1
803	2 609 000 868	Armature 230V	1
808	2 609 000 534	Nameplate	1
810	2 610 391 290	Carbon-Brush Set	1
816	2 609 000 871	Brush Holder	1
829	2 609 000 874	Vibration Foot	1
832	2 609 000 876	Sander Plate	1

Illustration - Type - E

3 603 C40 100
 Stand } DE-61
 Issue } 10-03-26

Fig. /Abb. 1

