



1	341164430	screw bag f. CS 22-355
2	341117740	Handle
3	316073370	Gear-box compl. Quick
4	143110480	Grooved ball bearing 17x40x12
5	141180100	Retaining ring
6	143111120	Ball bearing, 10x26x8
7	315106740	Gear Housing
8	316073380	Spindle stop compl.
9	339153160	Baffle
10	143114870	Ball bearing, 15x35x11
11	310013540	Armature
12	143114800	Ball bearing, 12x28x8
13	344104010	Rubber buffer
14	311013610	Field w.coil
15	343456590	Motor housing
16	316073410	Brush holder Set cpl.
17	316073510	Carbon brush compl.
18	316073500	Cover cap cpl.
19	343456600	Top cover
20	344104020	Rubber plug
21	316073420	Handle cpl.
22	343456610	Switch trigger
23	343456630	Switch
24	343255340	Suppressor
25	343441950	CABLE CLAMP
26	344104040	COUPLING f. cable
27	344533520	Cable with plug 230V
28	339206920	Wheel guard
29	341032390	Flange
30	341006880	Spacer sleeve
31	344104050	O-ring
32	316073520	Fastening screw cpl.
33	316098680	Moving guard comp.
34	339145940	slip case
35	316073440	SPARK PROTECTOR ASSEMBLY

36	316073450	Saw head lock comp.
37	339141530	Angle stop
38	342024660	Spring
39	341516930	Shoulder bolt
40	316073460	Lever ass'y
41	316073470	Depth stop compl.
42	344104030	Rubber bushing
43	344162620	ALLEN HEXAGON KEY SW 8X100/3
44	316073480	Rubber feet compl.
45	316073490	Base plate compl.
46	338078090	rating plate 01786000 CS 22-355
48	399999990	Part not needed
880	344131500	Gear grease
1001	338510820	Wiring diagram